<u>CABLE PLUS XXL \rightarrow LOCKING PROCEDURE</u>




Diagram A




Diagram B

STEP 1

Make sure the seal is being placed with the front side facing the user, as shown in Diagram A.

STEP 2

Hold the seal using one hand and with the other, insert the locking head into the entry hole, as shown in Diagram B.




Diagram C

STEP 3

After inserting, push the locking head in till the maximum until you hear a "click" sound to indicate sealing, as shown in Diagram C.